








DRAWN 5-20-75
BY
W. SYCKS










Originally recorded distance
evidently in error: 2700.06 in
Surveyor's Log, but closer to
2960

Originally recorded distance
evidently in error: 2659.80 in
Surveyor's Log, but closer to
2925

Needs new point
of origin

Needs new
point of
origin.


DRAWN 6-3-75
W. SYCKS



[illegible]

W. SYCKS

BEAN BLOSSOM
SECTION 9, TOWNSHIP 10 NORTH, RANGE 2 WEST



Drawn 5-12-75
W. Syck's

SECTION 10, TOWNSHIP 10 NORTH, RANGE 2 WEST

2640

2678.28

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

BRIGHTON ROAD

MT. TABOR RD.

FULFORD LANE

BOTTOM ROAD

UNIMPROVED ROAD

NEEDS SURVEY

NEEDS NEW DESCRIPTION

NO RECORD


2640

2640

2640

W. SYCKS

SECTION 11, TOWNSHIP 10 NORTH, RANGE 2 WEST ^{BEAN BLOSSOM}



DRAWN 5-7-75

W. SYCKS

Accumulative SKEW
-83.16

2640

2547.60

OVERLAP

NEEDS SURVEY

NEEDS SURVEY

NEEDS SURVEY

NEEDS SURVEY

NEEDS SURVEY

NEEDS SURVEY

NEEDS SURVEY

NEEDS SURVEY AND NEW DESCRIPTION

NEEDS SURVEY AND NEW DESCRIPTION

NEEDS NEW DESCRIPTION

Indian Boundary Line
ENCROACHMENT BY #18


Encroachment
by #13

2640

2630.76


W. SYCKS

BEAN BLOSSOM
SECTION 13, TOWNSHIP 10 NORTH, RANGE 2 WEST



DRAWN 4.16.75
W. D. SYCKS

SECTION 14, TOWNSHIP 10 NORTH, RANGE 2 WEST ^{BEAN BLOSSOM}




DRAWN 4.21.75
W. SYCKS

SECTION 15, TOWNSHIP 10 NORTH, RANGE 2 WEST




W. SYCKS

SECTION 16, TOWNSHIP 10 NORTH, RANGE 2 WEST



W. SYCKS


SECTION 17, TOWNSHIP 10 NORTH, RANGE 2 WEST



DRAWN 4-29-75


W. SYCKS

BEAN BLOSSOM
SECTION 18, TOWNSHIP 10 NORTH, RANGE 2 WEST



DRAWN 4-30-75
W. SYCKS


BEAN BLOSSOM
SECTION 19, TOWNSHIP 10 NORTH, RANGE 2 WEST



DRAWN 4.11.75

W. SYCKS

BEAN BLOSSOM
SECTION 20, TOWNSHIP 10 NORTH, RANGE 2 WEST



DRAWN 4.10.75

W. Sycks

Accumulative Skew
- 87.12

BEAN BLOSSOM

2640

2640

2628.12

1314.06

2640

2628.12

2640

2640

2034.06

2640

WALKER ROAD

HILL ROAD

HEDRICK ROAD

RED HILL

2

16

4

5

6

3

15

14

17

4

7

8

13

10

11

9

12

OVERLAP


NEEDS SURVEY

OVERLAP;

NEEDS SURVEY

DRAWN 4.7.75
W. SYCKS

SECTION 22, TOWNSHIP 10 NORTH, RANGE 2 WEST
BEAH BLOSSOM



Accumulative SKEW
-69.30

BEAN BLOSSOM

2635.38

2635.38

2640

2640

2654.85

2654.85

WOODLAND

BARR ROAD

ROAD

BEAN BLOSSOM CREEK

NEEDS NEW DESCRIPTION


NEEDS SURVEY

NEEDS SURVEY


NEEDS NEW DESCRIPTION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25

ACCUMULATIVE
SKEW
- 30.36




BEAN BLOSSOM — SECTION 25 — TOWNSHIP 10 NORTH — RANGE 2 WEST




SECTION 26, TOWNSHIP 10 NORTH, RANGE 2 WEST

BEAN BLOSSOM




SECTION 27, TOWNSHIP 10 NORTH, RANGE 2 WEST




DRAWN MAR. '75
W. SYCKS

BEAN BLOSSOM
SECTION 28, TOWNSHIP 10 NORTH, RANGE 2 WEST




[illegible]


SECTION 30, TOWNSHIP 10 NORTH, RANGE 2 WEST




SECTION 31, TOWNSHIP 10 NORTH, RANGE 2 WEST




SECTION 32, TOWNSHIP 10 NORTH, RANGE 2 WEST




SECTION 33, TOWNSHIP 10 NORTH, RANGE 2 WEST



SECTION 34, TOWNSHIP 10 NORTH, RANGE 2 WEST



SECTION 35, TOWNSHIP 10 NORTH, RANGE 2 WEST



SECTION 36, TOWNSHIP 10 NORTH, RANGE 2 WEST

